Boston, MA 02129

Tel: 617.886.7400

Fax: 617.886.7600 HaleyAldrich.com



8 January 2015 File No. 10063-240

Massachusetts Department of Environmental Protection 205B Lowell Street Wilmington, Massachusetts 01887

Attention: Mr. Jack Miano

Subject: Notice of Placement in Public Repositories

Protective Cover Monitoring Plan (PCMP) Inspection Report No. 41

W.R. Grace & Co. Properties

62 Whittemore Avenue, One Alewife Center, 134 Alewife Brook Parkway

Cambridge, Massachusetts RTNs 3-0277 and 3-3411

Dear Mr. Miano:

This letter is to inform you of the placement of the above-referenced document in five public repositories. A list of the repositories and contact information is attached.

In accordance with the Activity and Use Limitations (AUL) recorded for the W.R. Grace Site and the Former Lehigh Metals and Babo's Site in March 2006, W.R. Grace & Co. engaged an LSP to implement a Protective Cover Monitoring Plan (PCMP). On 15 December 2014 Haley & Aldrich and W.R. Grace conducted a site inspection in accordance with the PCMP, dated March 2006. PCMP Inspection Report No. 41 was prepared during the site walkover and copies have been placed in the public repositories.

PCMP inspections were conducted monthly for the first year, April 2006 to April 2007, and have been conducted quarterly in subsequent years. Copies of the inspection reports are placed into the public repositories following each inspection. This letter serves as notice of placement of the quarterly inspection reports into the public repositories.

If you have any questions, please do not hesitate to call the undersigned.

Sincerely yours,

HALEY & ALDRICH, INC.

Jennifer L. Sweet, P.E, LSP

ber west

Senior Engineer

**Enclosure** 

c: W.R. Grace PIP Notification and Mailing List Information Sheet

## **Notification and Mailing List**

Updated 1 July 2013 W.R. Grace & Co.-Conn. Cambridge, Massachusetts RTN 3-0277

## **Notification List**

Sam Lipson City of Cambridge Director of Environmental Health Cambridge Public Health Department 119 Windsor Street Cambridge, MA 02139

Cambridge City Hall City Manager's Office 795 Massachusetts Avenue Cambridge, MA 02139

Richard Rossi

## **Mailing List**

\*\*\*Lisa Birk
Member
Alewife Study Group
20 Kassul Park
Cambridge, MA 02140

Dick Clarey Chair North Cambridge Stabilization Committee 15 Brookford Street Cambridge, MA 02140

Hannah Goodwin
Officer
Alewife Neighbors, Inc.

94 Clifton Street Cambridge, MA 02140 \*\*\*Joe Joseph Member Alewife Study Group 20 Kassul Park Cambridge, MA 02140

\*\*\*Mike Nakagawa

Officer Alewife Neighbors, Inc. 51 Madison Avenue Cambridge, MA 02140

**Mary White** 

Member, Alewife Study Group Resident, Cornerstone 175 Harvey Street, Apt. 9 Cambridge, MA 02140

\*\*\*Indicates representatives that also get hard copies of bound reports.

 $\label{lem:condition} \textbf{G:\normalfine} \ \textbf{C:\normalfine} \ \textbf{C:\nor$ 

## **INFORMATION SHEET**

## PUBLIC INFORMATION REPOSITORIES

**Department of Environmental Protection** 

Northeast Regional File Review Office

205B Lowell Street

Wilmington, Massachusetts 01887

Telephone: 978-694-3320

File Review Hours: Tuesday and Thursday: 9:00 am to 12:00 pm

**Cambridge Main Library** 

449 Broadway

Cambridge, Massachusetts 02138

Contact: Susan Flannery Telephone: 617-349-4040

File Review Hours: Monday-Thursday: 9 am to 9 pm

Friday-Saturday: 9 am to 5 pm

Sunday: 1 pm to 5 pm

North Cambridge Library

(O'Neill Branch)

70 Rindge Avenue

Cambridge, Massachusetts 02140

Contact: Lyndsay Forbes Telephone: 617-349-4023

File Review Hours: Monday & Wednesday: 10:00 am to 8:00 pm

Thursday & Friday: 10:00 am to 6 pm

Closed Tuesdays

City of Cambridge

Cambridge Public Health Department

119 Windsor Street

Cambridge, Massachusetts 02139

Contact: Sam Lipson Telephone: 617-665-3800

File Review Hours: Monday-Friday 8:30 am to 5:00 pm

## **Contact Information:**

W.R. Grace Contact: David Agresti

W.R. Grace & Co.-Conn. 62 Whittemore Avenue

Cambridge, Massachusetts 02140 Telephone: 617-876-1400

Haley & Aldrich, Inc. Contact: Jennifer Sweet

Haley & Aldrich, Inc.

465 Medford Street, Suite 2200 Boston, Massachusetts 02129 Telephone: 617-886-7411

 $G:\label{locality} G:\label{locality} G:\label{locality} Inspections \end{area} No 41-Dec 2014 \end{area} 2015-0108-INFOSHT. doc$ 



Tel: 617.886.7400 Fax: 617.886.7600 HaleyAldrich.com

8 January 2015 File No. 10063-240

Massachusetts Department of Environmental Protection 205B Lowell Street Wilmington, Massachusetts 01887

Attention: Jack Miano

Subject: W.R. Grace & Co.-Conn.

62 Whittemore Avenue, One Alewife Center, and

134 Alewife Brook Parkway Cambridge, Massachusetts RTNs 3-0277 and 3-3411

Dear Mr. Miano:

On behalf of W.R. Grace & Co.-Conn., we are submitting the Protective Cover Monitoring Plan (PCMP) Inspection Report No. 41. Haley & Aldrich completed the site inspection on 15 December 2014 in accordance with the PCMP, dated March 2006. Results of the inspection are provided in the attached log report. Please contact the undersigned if you have any questions.

Sincerely yours,

HALEY & ALDRICH, INC.

Jennifer L. Sweet, P.E., LSP

west

Senior Engineer

**Enclosures** 

PCMP Inspection Report No. 41

c: PIP Repositories:

W.R. Grace & Co.-Conn Cambridge Main Library North Cambridge Library

Cambridge Public Health Department

City Manager, City of Cambridge; Attn: Richard Rossi

G:\10063\PCMP Inspections\No41-Dec2014\2015-0108-HAI\_Grace PCMP No. 41-cover ltr\_F.doc

### HALEY& ALDRICH PROTECTIVE COVER MONITORING PLAN INSPECTION REPORT **Project** W.R. Grace & Co.-Conn. Report No. 62 Whittemore Avenue, One Alewife Center, Location Date 15 December 2014 134 Alewife Brook Parkway Cambridge, Massachusetts Address Page 1 of 6 Client W.R. Grace & Co. File No. 10063-240 Weather 40s° Clear **Temperature** Field Rep. Jennifer Sweet, Dave Croce LSP Jennifer L. Sweet, P.E., LSP 1. **Protective Cover Surface Observations: Area 1 Conditions:** Is Protective Cover in Area 1 observed to be in same conditions compared to "baseline

| Yes No | conditions"? If no, describe change(s) in conditions:   |
|--------|---|
| •      |   |
| Yes No | Are there bare spots, signs of erosion, or large potholes in pavement? (If yes, attach photographs and figure showing location and extent) Describe eroded area or areas of potholes: |
|        |   |
| Yes No | Is there any Asbestos Containing Material (ACM) observed at the ground surface:   |
| 1 -    | Other Observations:   |

## A

Other Observations: \_\_\_

| Area 2 Conditio | ons:  |
|-----------------|---|
| Yes No          | Is Protective Cover in Area 2 observed to be in same conditions compared to "baseline conditions"? If no, describe change(s) in conditions:             |
| Yes No          | Are there bare spots, signs of erosion? (If yes, attach photographs and figure showing location and extent): Describe eroded area or areas of potholes: |
| Yes No          | Is there any Asbestos Containing Material (ACM) observed at the ground surface:   |

| HALEY&<br>ALDRICH |  |
|-------------------|--|
|                   |  |

## PROTECTIVE COVER MONITORING PLAN INSPECTION REPORT

| Project    | W.R. Grace & CoConn.   | Report No.             | 41               |
|------------|--|------------------------|------------------|
| Location   | 62 Whittemore Avenue, One Alewife Center,  | Date                   | 15 December 2014 |
|            | 134 Alewife Brook Parkway  | _                      |                  |
| Address    | Cambridge, Massachusetts   | Page                   | 2 of 6           |
| Client     | W.R. Grace & Co.   | File No.               | 10063-240        |
| Weather    | Clear  | Temperature            | 40s°             |
| Field Rep. | Jennifer Sweet, Dave Croce   |                        |                  |
| LSP        | Jennifer L. Sweet, P.E., LSP   |                        |                  |
| Arc        | ea 3 Conditions:   |                        |                  |
| (          | Yes No Is Protective Cover in Area 3 observed to be in san conditions"? If no, describe change(s) in conditions        |                        |                  |
|            |  |                        |                  |
|            | Yes No and extent) Describe eroded area or areas of pothol   |                        |                  |
|            |  |                        |                  |
|            | Yes No Is there any Asbestos Containing Material (ACM) of  | observed at the ground | 1 surface:       |
| <u> </u>   |  |                        |                  |
|            | Other Observations:  |                        |                  |
|            |  |                        |                  |
|            |  |                        |                  |
| Arc        | ea 4 Conditions:   |                        |                  |
|            | Yes No Is Protective Cover in Area 4 observed to be in san conditions"? If no, describe change(s) in conditions        | -                      |                  |
|            |  |                        |                  |
|            | Yes No Are there bare spots, signs of erosion? (If yes, attaction and extent): Describe eroded area or areas of pothor |                        | _                |
|            |  |                        |                  |
| Γ          | Yes No Is there any Asbestos Containing Material (ACM)   | observed at the ground | 1 surface:       |
|            |  |                        |                  |
|            | Other Observations:  |                        |                  |
|            | · ·  |                        |                  |
|            | -  |                        |                  |

#### HALEY& ALDRICH PROTECTIVE COVER MONITORING PLAN INSPECTION REPORT **Project** W.R. Grace & Co.-Conn. Report No. 62 Whittemore Avenue, One Alewife Center, Location Date 15 December 2014 134 Alewife Brook Parkway Cambridge, Massachusetts Address 3 of 6 Page Client W.R. Grace & Co. File No. 10063-240 40s° Weather Clear **Temperature** Field Rep. Jennifer Sweet, Dave Croce LSP Jennifer L. Sweet, P.E., LSP

## **Area 5 Conditions:**

| Yes No          | Is Protective Cover in Area 5 observed to be in same conditions compared to "baseline conditions"? If no, describe change(s) in conditions:   |
|-----------------|---|
| Yes No          | Are there bare spots, signs of erosion? (If yes, attach photographs and figure showing location and extent) Describe eroded area or areas of potholes:                                  |
| Yes No          | Is there any Asbestos Containing Material (ACM) observed at the ground surface:   |
|                 | Other Observations:   |
| Area 6 Conditio | ns:   |
| Yes No          | Is Protective Cover in Area 6 observed to be in same conditions compared to "baseline conditions"? If no, describe change(s) in conditions:   |
| Yes No          | Are there bare spots, signs of erosion, or large potholes in pavement? (If yes, attach photographs and figure showing location and extent) Describe eroded area or areas of potholes: _ |
| Yes No          | Is there any Asbestos Containing Material (ACM) observed at the ground surface:   |
|                 | Other Observations:   |
|                 |   |

# HALEY& ALDRICH

## PROTECTIVE COVER MONITORING PLAN INSPECTION REPORT

| Project   |                 | . Grace & CoConn.  | Report No.            | 41<br>15 D             |
|-----------|-----------------|--|-----------------------|------------------------|
| Location  |                 | Thittemore Avenue, One Alewife Center, Alewife Brook Parkway | Date                  | 15 December 2014       |
| Address   |                 | bridge, Massachusetts  | Page                  | 4 of 6                 |
| Client    |                 | . Grace & Co.  | File No.              | 10063-240              |
| Weather   | Clean           | r  | Temperature           | 40s°                   |
| Field Rep | . Jenni         | ifer Sweet, Dave Croce                                       |                       |                        |
| LSP       | Jenni           | ifer L. Sweet, P.E., LSP                                     |                       |                        |
| A         | rea 7 Condition | ns:  |                       |                        |
|           |                 |  |                       |                        |
|           | Yes No          | Is Protective Cover in Area 7 observed to be in same co      | onditions compared    | to "baseline           |
|           | 103             | conditions"? If no, describe change(s) in conditions:        |                       |                        |
| _         |                 |  |                       |                        |
| Γ         | Yes No          | Are there bare spots or signs of erosion? (If yes, attach    | photographs and fi    | igure showing location |
|           | 165             | and extent) Describe eroded area or areas of potholes:       |                       |                        |
|           |                 |  |                       |                        |
| Г         |                 | Is there any Asbestos Containing Material (ACM) observed     | rved at the ground    | surface:               |
|           | Yes No          |  | C                     |                        |
|           |                 | Other Observations:  |                       |                        |
|           |                 |  |                       |                        |
|           |                 |  |                       |                        |
| A         | rea 8 Condition | ns:  |                       |                        |
|           |                 |  |                       |                        |
|           | Yes No          | Is Protective Cover in Area 8 observed to be in same co      | onditions compared    | to "baseline           |
|           |                 | conditions"? If no, describe change(s) in conditions:        |                       |                        |
|           |                 |  |                       |                        |
| Г         |                 | Are there signs of erosion or large potholes in pavemen      | nt? (If wes lattach n | hotographs and figure  |
|           | Yes No          |  | _                     |                        |
| L         |                 | showing location and extent) Describe eroded area or a       | reas of potholes:     |                        |
|           |                 |  |                       |                        |
| Г         |                 | Is there any Asbestos Containing Material (ACM) observed     | rved at the ground    | ourfood.               |
|           | Yes No          | is there any Asocstos Containing Material (ACM) obse         | ived at the ground    | surface.               |
| L         |                 |  |                       |                        |
|           |                 | Other Observations:  |                       |                        |
|           |                 |  |                       |                        |
|           |                 |  |                       |                        |

| HALEY&<br>ALDRICH                                 | PROTECTIVE COVER MONITORING P  | PLAN INSPECTION                 | REPORT                      |
|---|--|---------------------------------|-----------------------------|
| Project<br>Location                               | <ul><li>W.R. Grace &amp; CoConn.</li><li>62 Whittemore Avenue, One Alewife Center,</li><li>134 Alewife Brook Parkway</li></ul> | Report No.<br>Date              | 41<br>15 December 2014      |
| Address<br>Client<br>Weather<br>Field Rep.<br>LSP | Cambridge, Massachusetts W.R. Grace & Co. Clear Jennifer Sweet, Dave Croce Jennifer L. Sweet, P.E., LSP                        | Page<br>File No.<br>Temperature | 5 of 6<br>10063-240<br>40s° |
| 2.  | Interview with Owner Representative  |                                 |                             |
| Name  | of Owner's Representative interviewed: <u>David Croce</u>  |                                 |                             |
| Any no  | ew buildings or structures on the Site? No   |                                 |                             |
| Any ch  | nanges in use of the existing buildings? No  |                                 |                             |
| Any cl  | nanges in use of un-built areas? No  |                                 |                             |
| Any ev  | vidence of active recreation? No   |                                 |                             |
| Any cu  | urrent activities that would degrade the Protective Cover?   | No                              |                             |
| Any ev  | vidence of property use for cultivation of fruits and vegetal  | bles for human consumption      | on? No                      |
| Has th  | ere been any emergency utility work conducted since the la   | ast inspection? No.             |                             |
| 3.  | Maintenance/Repair Actions to be Taken   |                                 |                             |
| Ye  | Were there changes in the Protective Cover not   |                                 | hat require actions to b    |

| Were there changes in the Protective Cover noted during the inspection that require actions to be |
|---|
| taken to maintain and/or repair the Cover? If yes, describe:                                      |
|   |
|   |
|   |

## 4. Other Comments:


## HALEY& **ALDRICH** PROTECTIVE COVER MONITORING PLAN INSPECTION REPORT W.R. Grace & Co.-Conn. **Project** Report No. 62 Whittemore Avenue, One Alewife Center, Location Date 15 December 2014 134 Alewife Brook Parkway Address Cambridge, Massachusetts Page 6 of 6 Client W.R. Grace & Co. File No. 10063-240 40s° Weather Clear **Temperature** Field Rep. Jennifer Sweet, Dave Croce **LSP** Jennifer L. Sweet, P.E., LSP Figure 1: PCMP – Site Orthophoto **ATTACHMENTS:** (Check off attachments) Photographs (List and note photo location/orientation on figure)

G:\10063\PCMP Inspections\No41-Dec2014\2014-1215-HAI\_Grace PCMP Checklist.doc

Haley & Aldrich, Inc.



INSPECTION PHOTOGRAPHS




EXISTING STRUCTURE AREA OF INTEREST

EXISTING WATER BODY

APPROXIMATE LIMITS OF AUL

- 1. ALL LOCATIONS, DIMENSIONS AND SITE FEATURES ARE APPROXIMATE.
- 2. 1/2 METER RESOLUTION ORTHOPHOTOGRAPHY FLOWN IN 2001 OBTAINED FROM THE OFFICE OF GEOGRAPHIC AND ENVIRONMENTAL INFORMATION (MASSGIS), COMMONWEALTH OF MASSACHUSETTS EXECUTIVE OFFICE OF ENVIRONMENTAL AFFAIRS.



HALEY& W.R. GRACE & CO. - CONN.
62 WHITEMORE AVENUE
PROTECTIVE COVER MONITORING PLAN
CAMBRIDGE, MASSACHUSETTS

SITE ORTHOPHOTO

SCALE: AS SHOWN DECEMBER 2014

FIGURE 1



















**A2-1** 




A2-2



**A2-3** 



**A2-4** 



A3-1



A3-2



A3-3



A4-1



A4-2



A4-3



A5-1



A5-2






A7-1



A7-2





**A8-1** 



A8-2



A8-3



A8-4