Haley & Aldrich, Inc. 465 Medford St. Suite 2200 Boston, MA 02129

Tel: 617.886.7400 Fax: 617.886.7600 HaleyAldrich.com



20 December 2011 File No. 10063-066

Massachusetts Department of Environmental Protection 205B Lowell Street Wilmington, Massachusetts 01887

Attention: Mr. Jack Miano

Subject: Notice of Placement in Public Repositories Protective Cover Monitoring Plan (PCMP) Inspection Report No. 30 W.R. Grace & Co. Properties 62 Whittemore Avenue, One Alewife Center, 134 Alewife Brook Parkway Cambridge, Massachusetts RTNs 3-0277 and 3-3411

Dear Mr. Miano:

This letter is to inform you of the placement of the above-referenced document in five public repositories. A list of the repositories and contact information is attached.

In accordance with the Activity and Use Limitations (AUL) recorded for the W.R. Grace Site and the Former Lehigh Metals and Babo's Site in March 2006, W.R. Grace & Co. engaged an LSP to implement a Protective Cover Monitoring Plan (PCMP). On 8 December 2011 Haley & Aldrich and W.R. Grace conducted a site inspection in accordance with the PCMP, dated March 2006. PCMP Inspection Report No. 30 was prepared during the site walkover and copies have been placed in the public repositories.

PCMP inspections were conducted monthly for the first year, April 2006 to April 2007, and have been conducted quarterly in subsequent years. Copies of the inspection reports are placed into the public repositories following each inspection. This letter serves as notice of placement of the quarterly inspection reports into the public repositories.

If you have any questions, please do not hesitate to call the undersigned.

Sincerely yours, HALEY & ALDRICH, INC.

John R. Kastrinos, P.G., LSP Senior Hydrogeologist

Enclosure c: W.R. Grace PIP Notification and Mailing List G:\10063\PCMP Inspections\No30-Dec2011\2011-1220-HAI-PIP Notice_PCMP No 30.doc

Notification and Mailing List

W.R. Grace & Co.-Conn. Cambridge, Massachusetts RTN 3-0277

Notification List

City of Cambridge Director of Environmental Health Cambridge Public Health Department 119 Windsor Street Cambridge, MA 02139

Mailing List

***Lisa Birk

Member Alewife Study Group 20 Kassul Park Cambridge, MA 02140

Dick Clarey

Chair North Cambridge Stabilization Committee 15 Brookford Street Cambridge, MA 02140

Hannah Goodwin

Officer Alewife Neighbors, Inc. 94 Clifton Street Cambridge, MA 02140

Denise Guerin

President Alewife Neighbors, Inc. 125 Montgomery Street Cambridge, MA 02140 Cambridge City Hall City Manager's Office 795 Massachusetts Avenue Cambridge, MA 02139

****Joe Joseph* Member Alewife Study Group 20 Kassul Park Cambridge, MA 02140

***Mike Nakagawa

Officer Alewife Neighbors, Inc. 51 Madison Avenue Cambridge, MA 02140

Steve Schnapp

Member Alewife Study Group 32 Clay Street Cambridge, MA 02140

Mary White

Member, Alewife Study Group Resident, Cornerstone 175 Harvey Street, Apt. 9 Cambridge, MA 02140

***Indicates representatives that also get hard copies of bound reports.

G:\10063\PCMP Inspections\No30-Dec2011\Notification and Mailing List.docx

Haley & Aldrich, Inc. 465 Medford St. Suite 2200 Boston, MA 02129

Tel: 617.886.7400 Fax: 617.886.7600 HaleyAldrich.com



20 December 2011 File No. 10063-066

Massachusetts Department of Environmental Protection 205B Lowell Street Wilmington, Massachusetts 01887

Attention: Jack Miano

Subject: W.R. Grace & Co.-Conn. 62 Whittemore Avenue, One Alewife Center, and 134 Alewife Brook Parkway Cambridge, Massachusetts RTNs 3-0277 and 3-3411

Dear Mr. Miano:

On behalf of W.R. Grace & Co.-Conn., we are submitting the Protective Cover Monitoring Plan (PCMP) Inspection Report No. 30. Haley & Aldrich completed the site inspection on 8 December 2011 in accordance with the PCMP, dated March 2006. Results of the inspection are provided in the attached log report. Please contact the undersigned if you have any questions.

Sincerely yours, HALEY & ALDRICH, INC.

weit

Jennifer L. Sweet, P.E. Senior Engineer

Enclosures PCMP Inspection Report No. 30

c: PIP Repositories:

W.R. Grace & Co.-Conn Cambridge Main Library North Cambridge Library Cambridge Public Health Department City Manager, City of Cambridge; Attn: Mr. Robert Healy

G:\10063\PCMP Inspections\No30-Dec2011\2011-1220-PCMP cover letter_F.doc

HALEY& ALDRICH	PROTECTIVE COVER MONITORING PLAN	INSPECTION	REPORT
Project	W.R. Grace & CoConn.	Report No.	30
Location	62 Whittemore Avenue, One Alewife Center, 134 Alewife Brook Parkway	Date	8 December 2011
Address	Cambridge, Massachusetts	Page	1 of 6
Client	W.R. Grace & Co.	File No.	10063-066
Weather	Clear	Temperature	40s°
Field Rep.	Jennifer Sweet, Dave Croce	_	
LSP	John R. Kastrinos, P.G., LSP		

1. Protective Cover Surface Observations:

Area 1 Conditions:



Is Protective Cover in Area 1 observed to be in same conditions compared to "baseline conditions"? If no, describe change(s) in conditions:



Are there bare spots, signs of erosion, or large potholes in pavement? (If yes, attach photographs and figure showing location and extent): Describe eroded area or areas of potholes: <u>Three</u> excavations were recently completed within Area 1 to make emergency repairs to underground piping and valves of the existing building sprinkler system, a backflow preventer valve, and a small sinkhole (these areas are shown on the attached figure). The excavations were completed under a URAM (RTN 3-30341), which was orally approved by MassDEP on 29 September 2011. Excavations were completed within temporary enclosed structures under negative pressure, and perimeter dust and air monitoring was conducted during soil disturbing activities. Asbestos fibers were not detected in air samples collected. Further details will be provided in a URAM Completion Report to be submitted under separate cover.



Is there any Asbestos Containing Material (ACM) observed at the ground surface:

Other Observations:

Area 2 Conditions:



Is Protective Cover in Area 2 observed to be in same conditions compared to "baseline conditions"? If no, describe change(s) in conditions:



Are there bare spots, signs of erosion? (If yes, attach photographs and figure showing location and extent): Describe eroded area or areas of potholes:

HALEY& ALDRICH	PROTECTIVE COVER MONITORING PLAN INSPECTION REPORT		
Project	W.R. Grace & CoConn.	Report No.	30
Location	62 Whittemore Avenue, One Alewife Center, 134 Alewife Brook Parkway	Date	8 December 2011
Address	Cambridge, Massachusetts	Page	2 of 6
Client	W.R. Grace & Co.	File No.	10063-066
Weather	Clear	Temperature	40s°
Field Rep.	Jennifer Sweet, Dave Croce	-	
LSP	John R. Kastrinos, P.G., LSP		

Is there any Asbestos Containing Material (ACM) observed at the ground surface:

Other Observations:

Area 3 Conditions:

No



Yes

Is Protective Cover in Area 3 observed to be in same conditions compared to "baseline conditions"? If no, describe change(s) in conditions:



Are there bare spots, signs of erosion? (If yes, attach photographs and figure showing location and extent): Describe eroded area or areas of potholes:



Is there any Asbestos Containing Material (ACM) observed at the ground surface:

Other Observations:

Area 4 Conditions:



Is Protective Cover in Area 4 observed to be in same conditions compared to "baseline conditions"? If no, describe change(s) in conditions:



Are there bare spots, signs of erosion? (If yes, attach photographs and figure showing location and extent): Describe eroded area or areas of potholes:



Is there any Asbestos Containing Material (ACM) observed at the ground surface:

Other Observations:

HALEY& ALDRICH	PROTECTIVE COVER MONITORING PLAN INSPECTION REPORT		
Project	W.R. Grace & CoConn.	Report No.	30
Location	62 Whittemore Avenue, One Alewife Center, 134 Alewife Brook Parkway	Date	8 December 2011
Address	Cambridge, Massachusetts	Page	3 of 6
Client	W.R. Grace & Co.	File No.	10063-066
Weather	Clear	Temperature	40s°
Field Rep.	Jennifer Sweet, Dave Croce	-	
LSP	John R. Kastrinos, P.G., LSP		

Area 5 Conditions:



Is Protective Cover in Area 5 observed to be in same conditions compared to "baseline conditions"? If no, describe change(s) in conditions:



Are there bare spots, signs of erosion? (If yes, attach photographs and figure showing location and extent): Describe eroded area or areas of potholes:



Is there any Asbestos Containing Material (ACM) observed at the ground surface:

Other Observations:

Area 6 Conditions:



Is Protective Cover in Area 6 observed to be in same conditions compared to "baseline conditions"? If no, describe change(s) in conditions:



Are there bare spots, signs of erosion, or large potholes in pavement? (If yes, attach photographs and figure showing location and extent): Describe eroded area or areas of potholes:



Is there any Asbestos Containing Material (ACM) observed at the ground surface:

Other Observations:

HALEY& ALDRICH	PROTECTIVE COVER MONITORING PLAN	INSPECTION	REPORT
Project	W.R. Grace & CoConn.	Report No.	30
Location	62 Whittemore Avenue, One Alewife Center, 134 Alewife Brook Parkway	Date	8 December 2011
Address	Cambridge, Massachusetts	Page	4 of 6
Client	W.R. Grace & Co.	File No.	10063-066
Weather	Clear	Temperature	40s°
Field Rep.	Jennifer Sweet, Dave Croce		
LSP	John R. Kastrinos, P.G., LSP		

Area 7 Conditions:



Is Protective Cover in Area 7 observed to be in same conditions compared to "baseline conditions"? If no, describe change(s) in conditions:



Are there bare spots or signs of erosion? (If yes, attach photographs and figure showing location and extent): Describe eroded area or areas of potholes:



Is there any Asbestos Containing Material (ACM) observed at the ground surface:

Other Observations:

Area 8 Conditions:



Is Protective Cover in Area 8 observed to be in same conditions compared to "baseline conditions"? If no, describe change(s) in conditions:



Are there signs of erosion or large potholes in pavement? (If yes, attach photographs and figure showing location and extent): Describe eroded area or areas of potholes: ______



Is there any Asbestos Containing Material (ACM) observed at the ground surface:

Other Observations:

HALEY& ALDRICH	PROTECTIVE COVER MONITORING PLAN INSPECTION REPORT		
Project	W.R. Grace & CoConn.	Report No.	30
Location	62 Whittemore Avenue, One Alewife Center, 134 Alewife Brook Parkway	Date	8 December 2011
Address	Cambridge, Massachusetts	Page	5 of 6
Client	W.R. Grace & Co.	File No.	10063-066
Weather	Clear	Temperature	40s°
Field Rep.	Jennifer Sweet, Dave Croce	-	
LSP	John R. Kastrinos, P.G., LSP		

2. Interview with Owner Representative

Name of Owner's Representative interviewed: David Croce
Any new buildings or structures on the Site? <u>No</u>
Any changes in use of the existing buildings? <u>No</u>
Any changes in use of un-built areas? <u>No</u>
Any evidence of active recreation? <u>No</u>
Any current activities that would degrade the Protective Cover? No
Any evidence of property use for cultivation of fruits and vegetables for human consumption? <u>No</u>
Has there been any emergency utility work conducted since the last inspection? Yes, see notes under
Area 1 description.

3. Maintenance/Repair Actions to be Taken



Were there changes in the Protective Cover noted during the inspection that require actions to be taken to maintain and/or repair the Cover? If yes, describe: <u>See notes under Area 1 description</u>.

4. Other Comments:


HALEY& ALDRICH			REPORT	
Project	W.R. Grace & CoConn.	Report No.	30	
Location	62 Whittemore Avenue, One Alewife Center, 134 Alewife Brook Parkway	Date	8 December 2011	
Address	Cambridge, Massachusetts	Page	6 of 6	
Client	W.R. Grace & Co.	File No.	10063-066	
Weather	Clear	Temperature	40s°	
Field Rep.	Jennifer Sweet, Dave Croce	-		
LSP	John R. Kastrinos, P.G., LSP			

ATTACHMENTS:	Figure 1: PCMP – Site Orthophoto
(Check off attachments)	Photographs (List and note photo location/orientation on figure)
	□
	□

Jenfey Swart

G:\10063\PCMP Inspections\No30-Dec2011\PCMPCHECKLIST-8Dec11.doc

Haley & Aldrich, Inc.



LEGEND:




INSPECTION PHOTOGRAPHS DIRECTION OF PHOTOGRAPH

EXISTING STRUCTURE AREA OF INTEREST EXISTING WATER BODY APPROXIMATE LIMITS OF AUL

NOTES:

- 1. ALL LOCATIONS, DIMENSIONS AND SITE FEATURES ARE APPROXIMATE.
- 2. 1/2 METER RESOLUTION ORTHOPHOTOGRAPHY FLOWN IN 2001 OBTAINED FROM THE OFFICE OF GEOGRAPHIC AND ENVIRONMENTAL INFORMATION (MASSGIS), COMMONWEALTH OF MASSACHUSETTS EXECUTIVE OFFICE OF ENVIRONMENTAL AFFAIRS.



SCALE IN FEET



HALEY& ALDRICH W.R. GRACE & CO. - CONN. 62 WHITEMORE AVENUE PROTECTIVE COVER MONITORING PLAN CAMBRIDGE, MASSACHUSETTS

SITE ORTHOPHOTO

SCALE: AS SHOWN DECEMBER 2011

FIGURE 1











A1-4

Haley & Aldrich, Inc.





A1-6

Haley & Aldrich, Inc.





A1-8

Haley & Aldrich, Inc.



A2-1



A2-2

Haley & Aldrich, Inc.



Haley & Aldrich, Inc.

W.R. Grace & Co.- Conn. Cambridge, Massachusetts PCMP Inspection No. 30




A3-2





Haley & Aldrich, Inc.



Haley & Aldrich, Inc.

Cambridge, Massachusetts PCMP Inspection No. 30







A4-5



A5-1

Haley & Aldrich, Inc.





Haley & Aldrich, Inc.

Cambridge, Massachusetts PCMP Inspection No. 30



A7-3



A8-1

Haley & Aldrich, Inc.



A8-2





Haley & Aldrich, Inc.



A8-4