Tel: 617.886.7400 Fax: 617.886.7600 HaleyAldrich.com



8 October 2012 File No. 10063-141

Massachusetts Department of Environmental Protection 205B Lowell Street Wilmington, Massachusetts 01887

Attention: Mr. Jack Miano

Subject: Notice of Placement in Public Repositories

Protective Cover Monitoring Plan (PCMP) Inspection Report No. 33

W.R. Grace & Co. Properties

62 Whittemore Avenue, One Alewife Center, 134 Alewife Brook Parkway

Cambridge, Massachusetts RTNs 3-0277 and 3-3411

Dear Mr. Miano:

This letter is to inform you of the placement of the above-referenced document in five public repositories. A list of the repositories and contact information is attached.

In accordance with the Activity and Use Limitations (AUL) recorded for the W.R. Grace Site and the Former Lehigh Metals and Babo's Site in March 2006, W.R. Grace & Co. engaged an LSP to implement a Protective Cover Monitoring Plan (PCMP). On 13 September 2012 Haley & Aldrich and W.R. Grace conducted a site inspection in accordance with the PCMP, dated March 2006. PCMP Inspection Report No. 33 was prepared during the site walkover and copies have been placed in the public repositories.

PCMP inspections were conducted monthly for the first year, April 2006 to April 2007, and have been conducted quarterly in subsequent years. Copies of the inspection reports are placed into the public repositories following each inspection. This letter serves as notice of placement of the quarterly inspection reports into the public repositories.

If you have any questions, please do not hesitate to call the undersigned.

Sincerely yours,

HALEY & ALDRICH, INC.

John R. Kastrinos, P.G., LSP Senior Hydrogeologist

Enclosure

c: W.R. Grace PIP Notification and Mailing List

 $G:\label{loop} \begin{tabular}{ll} G:\label{loop} G:\label{loop} \begin{tabular}{ll} G:\label{loop} \begin{tabular}{ll}$

Notification and Mailing List

Updated 10 January 2012 W.R. Grace & Co.-Conn. Cambridge, Massachusetts RTN 3-0277

Notification List

City of Cambridge Director of Environmental Health Cambridge Public Health Department 119 Windsor Street Cambridge, MA 02139 Cambridge City Hall City Manager's Office 795 Massachusetts Avenue Cambridge, MA 02139

Mailing List

***Lisa Birk
Member
Alewife Study Group
20 Kassul Park
Cambridge, MA 02140

Dick ClareyChair
North Cambridge Stabilization Committee

15 Brookford Street Cambridge, MA 02140

Hannah Goodwin

Officer Alewife Neighbors, Inc. 94 Clifton Street Cambridge, MA 02140 ***Joe Joseph

Member Alewife Study Group 20 Kassul Park Cambridge, MA 02140

***Mike Nakagawa

Officer Alewife Neighbors, Inc. 51 Madison Avenue Cambridge, MA 02140

Mary White

Member, Alewife Study Group Resident, Cornerstone 175 Harvey Street, Apt. 9 Cambridge, MA 02140

***Indicates representatives that also get hard copies of bound reports.

 $G:\label{local_problem} G:\label{local_problem} In spections \label{local_problem} No 33-Sept 2012 \label{local_problem} Oo 33-Sept 2012 \label{local_problem} No 33-Sept 2012 \label{$

Tel: 617.886.7400 Fax: 617.886.7600 HaleyAldrich.com



File No. 10063-141

8 October 2012

Massachusetts Department of Environmental Protection 205B Lowell Street Wilmington, Massachusetts 01887

Attention: Jack Miano

Subject: W.R. Grace & Co.-Conn.

62 Whittemore Avenue, One Alewife Center, and

134 Alewife Brook Parkway Cambridge, Massachusetts RTNs 3-0277 and 3-3411

Dear Mr. Miano:

On behalf of W.R. Grace & Co.-Conn., we are submitting the Protective Cover Monitoring Plan (PCMP) Inspection Report No. 33. Haley & Aldrich completed the site inspection on 13 September 2012 in accordance with the PCMP, dated March 2006. Results of the inspection are provided in the attached log report. Please contact the undersigned if you have any questions.

Sincerely yours,

HALEY & ALDRICH, INC.

Jennifer L. Sweet, P.E. Senior Engineer

Enclosures

PCMP Inspection Report No. 33

c: PIP Repositories:

W.R. Grace & Co.-Conn
Cambridge Main Library
North Cambridge Library
Cambridge Public Health Den

Cambridge Public Health Department

City Manager, City of Cambridge; Attn: Mr. Robert Healy

 $G:\label{loop} $$G:\loop G:\loop G:\$

HALEY&	
ALDRICH	

PROTECTIVE COVER MONITORING PLAN INSPECTION REPORT

Project Location	W.R. Grace & CoConn. 62 Whittemore Avenue, One Alewife Center, 134 Alewife	Report No. Date	33 13 September 2012
Address Client Weather Field Rep. LSP	Brook Parkway Cambridge, Massachusetts W.R. Grace & Co. Clear Jennifer Sweet, Dave Croce John R. Kastrinos, P.G., LSP	Page File No. Temperature	1 of 6 10063-066 70s°
1.	Protective Cover Surface Observations:		
Ar	ea 1 Conditions:		
(Yes No Is Protective Cover in Area 1 observed to be in same co conditions"? If no, describe change(s) in conditions:	-	
	Yes No and figure showing location and extent): Describe erode		
	Yes No Is there any Asbestos Containing Material (ACM) obser	rved at the ground	surface:
	Other Observations:		
Ar	ea 2 Conditions:		
(Yes No Is Protective Cover in Area 2 observed to be in same co conditions"? If no, describe change(s) in conditions:	_	to "baseline
	Yes No Are there bare spots, signs of erosion? (If yes, attach ph extent): Describe eroded area or areas of potholes:		•
Γ	Yes No Is there any Asbestos Containing Material (ACM) obser		surface:
	Other Observations:		
	Other Observations:		

HA	LE	18z
ATI	DRI	CH

PROTECTIVE COVER MONITORING PLAN INSPECTION REPORT

Project	W.R. Grace & CoConn.	Report No.	33
Location	62 Whittemore Avenue, One Alewife Center, 134 Alewife Brook Parkway	Date	13 September 2012
Address	Cambridge, Massachusetts	Page	2 of 6
Client	W.R. Grace & Co.	File No.	10063-066
Weather	Clear	Temperature	$70\mathrm{s}^\circ$
Field Rep.	Jennifer Sweet, Dave Croce	-	
LSP	John R. Kastrinos, P.G., LSP		
Are	ea 3 Conditions:		
	Yes No Is Protective Cover in Area 3 observed to be in same co conditions"? If no, describe change(s) in conditions:	-	
	Yes No Are there bare spots, signs of erosion? (If yes, attach phextent): Describe eroded area or areas of potholes:		
	Yes No Is there any Asbestos Containing Material (ACM) obser	C	
	Other Observations:		
Are	ea 4 Conditions:		
	Yes No Is Protective Cover in Area 4 observed to be in same co conditions"? If no, describe change(s) in conditions:	-	
	Yes No Are there bare spots, signs of erosion? (If yes, attach ph extent): Describe eroded area or areas of potholes:	0 1	C
	Yes No Is there any Asbestos Containing Material (ACM) obser	· ·	surface:
<u> </u>	Other Observations:		

HALEY& ALDRICH PROTECTIVE COVER MONITORING PLAN INSPECTION REPORT

Project Location Address Client Weather Field Rep LSP	62 V Broo Cam W.R Clea	Whittemore Avenue, One Alewife Center, 134 Alewife ok Parkway abridge, Massachusetts a. Grace & Co. ur aifer Sweet, Dave Croce a R. Kastrinos, P.G., LSP	Page File No. Temperature	33 13 September 2012 3 of 6 10063-066 70s°
A	Area 5 Conditio	ns:		
	Yes No	Is Protective Cover in Area 5 observed to be in same co conditions"? If no, describe change(s) in conditions:	-	
	Yes No	Are there bare spots, signs of erosion? (If yes, attach phextent): Describe eroded area or areas of potholes:		
	Yes No	Is there any Asbestos Containing Material (ACM) obser	rved at the ground	surface:
		Other Observations:		
A	Area 6 Condition Yes No	Is Protective Cover in Area 6 observed to be in same co conditions"? If no, describe change(s) in conditions:	-	
	Yes No	Are there bare spots, signs of erosion, or large potholes and figure showing location and extent): Describe erode		
	Yes No	Is there any Asbestos Containing Material (ACM) obser	-	surface:
		Other Observations:		

H	LE	Y&
AT	DR	ICH

W.R. Grace & Co.-Conn.

62 Whittemore Avenue, One Alewife Center, 134 Alewife

Project

Location

PROTECTIVE COVER MONITORING PLAN INSPECTION REPORT

Report No.

13 September 2012

Date

Address Client Weather Field Rep LSP	W.R. Graden Clear Jennifer S	e, Massachusetts]	Page File No. Femperature	4 of 6 10063-066 70s°
A	Area 7 Conditions:				
	(Yes) No	otective Cover in Area 7 observed to itions"? If no, describe change(s) in		_	
	Yes (No)	there bare spots or signs of erosion?	-	• •	
	Yes No Is th	ere any Asbestos Containing Materi			
	Othe	r Observations:			
A	(Yes) No	otective Cover in Area 8 observed to		•	
	conc	itions"? If no, describe change(s) in	conditions:		
	168 (NO)	there signs of erosion or large pothoring location and extent): Describe			
	Yes No Is th	ere any Asbestos Containing Materi	al (ACM) observe	ed at the ground s	surface:
	Othe	r Observations:			

HALEY& ALDRICH	PROTECTIVE COVER MONITORING PLAN	INSPECTION	REPORT
Project Location	W.R. Grace & CoConn. 62 Whittemore Avenue, One Alewife Center, 134 Alewife	Report No. Date	33 13 September 2012 5 of 6 10063-066 70s°
Address Client Weather Field Rep. LSP	Brook Parkway Cambridge, Massachusetts W.R. Grace & Co. Clear Jennifer Sweet, Dave Croce John R. Kastrinos, P.G., LSP	Page File No. Temperature	
2.	Interview with Owner Representative		
Name	of Owner's Representative interviewed: <u>David Croce</u>		
Any ne	ew buildings or structures on the Site? No		
Any ch	nanges in use of the existing buildings? No		
Any ch	nanges in use of un-built areas? No		
Any ev	vidence of active recreation? No		
Any cı	urrent activities that would degrade the Protective Cover? No		
Any ev	vidence of property use for cultivation of fruits and vegetables for h	numan consumption	n? <u>No</u>
Has the	ere been any emergency utility work conducted since the last inspe	ction? No	
3.	Maintenance/Repair Actions to be Taken		
Ye	Were there changes in the Protective Cover noted durin taken to maintain and/or repair the Cover? If yes, description	-	•

HALEY& PROTECTIVE COVER MONITORING PLAN INSPECTION REPORT ALDRICH **Project** W.R. Grace & Co.-Conn. Report No. Location 62 Whittemore Avenue, One Alewife Center, 134 Alewife 13 September 2012 Date **Brook Parkway** Address Cambridge, Massachusetts Page 6 of 6 Client W.R. Grace & Co. File No. 10063-066 70s° Weather Clear Temperature Jennifer Sweet, Dave Croce Field Rep. LSP John R. Kastrinos, P.G., LSP **ATTACHMENTS:** Figure 1: PCMP – Site Orthophoto Photographs (List and note photo location/orientation on figure) (Check off attachments)


 $G:\label{local_pcmpchecklist} G:\label{local_pcmpchecklist} In spections \ \ No 33-Sept 2012 \ \ \ PCMPCHECKLIST-13 Sept 12. doc$

Haley & Aldrich, Inc.

Jenfer Sweet




INSPECTION PHOTOGRAPHS



EXISTING STRUCTURE AREA OF INTEREST

EXISTING WATER BODY APPROXIMATE LIMITS OF AUL

- 1. ALL LOCATIONS, DIMENSIONS AND SITE FEATURES ARE APPROXIMATE.
- 2. 1/2 METER RESOLUTION ORTHOPHOTOGRAPHY FLOWN IN 2001 OBTAINED FROM THE OFFICE OF GEOGRAPHIC AND ENVIRONMENTAL INFORMATION (MASSGIS), COMMONWEALTH OF MASSACHUSETTS EXECUTIVE OFFICE OF ENVIRONMENTAL AFFAIRS.



HALEY& W.R. GRACE & CO. - CONN.
62 WHITEMORE AVENUE
PROTECTIVE COVER MONITORING PLAN
CAMBRIDGE, MASSACHUSETTS

SITE ORTHOPHOTO

SCALE: AS SHOWN SEPTEMBER 2012

FIGURE 1



















A2-1



A2-2



A2-3



A3-1



A3-2



A3-3



A4-1



A4-2



A4-3



A4-4



A4-5



A5-1



A5-2



A5-3



A7-1



A7-2



A7-3



A8-1



A8-2



A8-3



A8-4