DEPARTMENT OF ENVIRONMENTAL PROTECTION WATERWAYS REGULATION PROGRAM

Notice of License Application pursuant to M. G. L. Chapter 91 Waterways License Application Number W08-2258 Dorchester Yacht Club


NOTIFICATION DATE: March 17, 2008


Public notice is hereby given of the application by Dorchester Yacht Club to replace and maintain existing piles with steel piles; and install and maintain steel beams within the locker deck at 100 Playstead Road in the municipality of Boston in and over flowed tidelands of Savin Hill Bay. The proposed use of the project is to provide access to navigable waters and to provide shoreline stabilization and is a water dependent project.

The Department will consider all written comments on this Waterways application received by within 30 days subsequent to the "Notification Date". Failure of any aggrieved person or group of ten citizens or more to submit written comments to the Waterways Regulation Program by the Public Comments Deadline will result in the waiver of any right to an adjudicatory hearing in accordance with 310 CMR 9.13(4)(c).

Additional information regarding this application may be obtained by contacting the Waterways Regulation Program at (617) 654-6520. Project plans and documents for this application are on file with the Waterways Regulation Program for public viewing, by appointment only, at the address below. Written comments must be addressed to: David Slagle, MassDEP - WRP, One Winter St., 5th fl., Boston, MA 02108.

MEGETVEL
MAR 1 8 2008






TYPICAL CROSS SECTION PILE SUPPORT SYSTEM WITH STEEL BEAM AT LOCKERS, DORCHESTER YACHT CLUB Mayflower Engr., Inc. 64 Joan Drive Quincy, Mass. 02169 617-376-0404

SHEET 2 OF 3 SHEETS

PROPOSED IMPROVEMENTS;

- NEW STEEL PILES AT LOCKERS AREA TO REINFORCE EXISTING SUPPORT SYSTEM.
- 2. NEW STEEL HORIZONTAL SUPPORT BEAMS ON THE PILES.
- 3. INSTALLATION OF SHIMS ON BEAMS TO SUPPORT WOOD STRINGERS.
- 4. ADDITIONAL WOOD STRINGERS TO SUPPORT LOCKERS.
- 5. ADDITIONAL WOOD STRINGERS @ CLUBHOUSE.
- 6. REPLACE EXISTING FLOATS THROUGHOUT AREA IN KIND & SIZE.
- 7. REPLACE SOME WOOD PILINGS.
- 8. REMOVE LIMITED OLD PILINGS AND DECKING.
- MAINTAIN EXISTING CONCRETE WALLS.
- 10. GENERAL CLEANUP OF AREA.
- 11. WORK IS PROPOSED OVER A 3-5 YEAR TIME FRAME.



PLAN OF FOUNDATION SUPPORT SYSTEM LOCKER AREA, DORCHESTER YACHT CLUB SCALE: AS SHOWN

Mayflower Engr., Inc. 64 Joan Drive Quincy, Mass. 02169 617-376-0404

SHEET 3 OF 3 SHEETS