

SCANNED

Haley & Aldrich, Inc.
465 Medford St.
Suite 2200
Boston, MA 02129-1400

Tel: 617.886.7400
Fax: 617.886.7600
HaleyAldrich.com

HALEY
ALDRICH

Letter of Transmittal

RECEIVED

OCT 19 2009

DEP
NORTHEAST REGIONAL OFFICE

Date 16 October 2009
File No. 10063-066
From Jennifer Sweet

To Massachusetts Department of Environmental Protection
205B Lowell Street
Wilmington, Massachusetts 01887

*PLEASE FILE UNDER

Attention Mr. Jack Miano

RTN # 3-277

Copy to PIP Repositories:

W.R. Grace & Co.-Conn
DEP Northeast File Review Office
Cambridge Main Library
North Cambridge Library

62 WHITTEMORE AVE
CAMBRIDGE

City Manager, City of Cambridge; Attn: Robert Healy
Cambridge Public Health Department; Attn: Sam Lipson
Alewife Study Group Member; Attn: Lisa Birk
Alewife Study Group Member; Attn: Joe Joseph
Alewife Neighbors, Inc. Attn: Mike Nakagawa

Subject W.R. Grace & Co.-Conn.
62 Whittemore Avenue, One Alewife Center, and
134 Alewife Brook Parkway
Cambridge, Massachusetts
RTNs 3-0277 and 3-3411

130 ALEWIFE BROOK PKWY

Copies	Date	Description
1	16 October 2009	Protective Cover Monitoring Plan (PCMP) Inspection Report No. 22

62 WHITTEMORE AVE

N/A-C

Transmitted via First class mail Overnight express Hand delivery Other

Remarks

For your files.

G:\10063\PCMP Inspections\No22-Oct2009\2009-1016-HAL-ItemNo.22\coverletter_DEP.doc

*See also:

3-3411
130 ALEWIFE BROOK PKWY
CAMBRIDGE

SCANNED

Haley & Aldrich
465 Medford St.
Suite 2200
Boston, MA 02129-1400

Tel: 617.886.7400
Fax: 617.886.7600
HaleyAldrich.com

**HALEY &
ALDRICH**

16 October 2009
File No. 10063-066

Massachusetts Department of Environmental Protection
205B Lowell Street
Wilmington, Massachusetts 01887

Attention: Jack Miano

Subject: W.R. Grace & Co.-Conn.
62 Whittemore Avenue, One Alewife Center, and
134 Alewife Brook Parkway
Cambridge, Massachusetts
RTNs 3-0277 and 3-3411

Dear Mr. Miano:

On behalf of W.R. Grace & Co.-Conn., we are submitting the Protective Cover Monitoring Plan (PCMP) Inspection Report No. 22. The Site inspection was completed by Haley & Aldrich on 12 October 2009 in accordance with the PCMP, dated March 2006. Results of the inspection are provided in the attached log report. Please contact the undersigned if you have any questions.

Sincerely yours,
HALEY & ALDRICH, INC.



Jennifer Sweet
Senior Engineer

Enclosures:

PCMP Inspection Report No. 22

c: PIP Repositories:

W.R. Grace & Co.-Conn
Cambridge Main Library
North Cambridge Library
Cambridge Health Alliance, Cambridge Public Health Department
City Manager, City of Cambridge; Attn: Mr. Robert Healy
Cambridge Public Health Department; Attn: Mr. Sam Lipson

G:\10063\PCMP Inspections\No22-Oct2009\2009-1016-PCMP coverletter_F.doc

* see also 3-3411
130 ALEWIFE BROOK PKWY
CAMBRIDGE

RECEIVED

OCT 19 2009

DEP
NORTHEAST REGIONAL OFFICE

PROTECTIVE COVER MONITORING PLAN INSPECTION REPORT

Project	W.R. Grace & Co.	Report No.	22
Location	62 Whittemore Avenue, One Alewife Center, 134 Alewife Brook Parkway	Date	12 October 2009
Address	Cambridge, Massachusetts	Page	1 of 6
Client	W.R. Grace & Co.	File No.	10063-066
Weather	Sunny	Temperature	55°
Field Rep.	Jennifer Sweet, Dave Croce		
LSP	John R. Kastrinos, P.G., LSP		

I. Protective Cover Surface Observations:

Area 1 Conditions:

Yes No Is Protective Cover in Area 1 observed to be in same conditions compared to "baseline conditions"? If no, describe change(s) in conditions: _____

Yes No Are there bare spots, signs of erosion, or large potholes in pavement? (If yes, attach photographs and figure showing location and extent): Describe eroded area or areas of potholes: _____

Yes No Is there any Asbestos Containing Material (ACM) observed at the ground surface: _____

Other Observations: _____

Area 2 Conditions:

Yes No Is Protective Cover in Area 2 observed to be in same conditions compared to "baseline conditions"? If no, describe change(s) in conditions: _____

Yes No Are there bare spots, signs of erosion? (If yes, attach photographs and figure showing location and extent): Describe eroded area or areas of potholes: _____

Yes No Is there any Asbestos Containing Material (ACM) observed at the ground surface: _____

Other Observations: _____

PROTECTIVE COVER MONITORING PLAN INSPECTION REPORT

Project	W.R. Grace & Co.	Report No.	22
Location	62 Whittemore Avenue, One Alewife Center, 134 Alewife Brook Parkway	Date	12 October 2009
Address	Cambridge, Massachusetts	Page	2 of 6
Client	W.R. Grace & Co.	File No.	10063-066
Weather	Sunny	Temperature	55°
Field Rep.	Jennifer Sweet, Dave Croce		
LSP	John R. Kastrinos, P.G., LSP		

Area 3 Conditions:

Yes No Is Protective Cover in Area 3 observed to be in same conditions compared to "baseline conditions"? If no, describe change(s) in conditions: _____

Yes No Are there bare spots, signs of erosion? (If yes, attach photographs and figure showing location and extent): Describe eroded area or areas of potholes: _____

Yes No Is there any Asbestos Containing Material (ACM) observed at the ground surface: _____

Other Observations: _____

Area 4 Conditions:

Yes No Is Protective Cover in Area 4 observed to be in same conditions compared to "baseline conditions"? If no, describe change(s) in conditions: _____

Yes No Are there bare spots, signs of erosion? (If yes, attach photographs and figure showing location and extent): Describe eroded area or areas of potholes: _____

Yes No Is there any Asbestos Containing Material (ACM) observed at the ground surface: _____

Other Observations: _____

PROTECTIVE COVER MONITORING PLAN INSPECTION REPORT

Project	W.R. Grace & Co.	Report No.	22
Location	62 Whittemore Avenue, One Alewife Center, 134 Alewife Brook Parkway	Date	12 October 2009
Address	Cambridge, Massachusetts	Page	3 of 6
Client	W.R. Grace & Co.	File No.	10063-066
Weather	Sunny	Temperature	55°
Field Rep.	Jennifer Sweet, Dave Croce		
LSP	John R. Kastornos, P.G., LSP		

Area 5 Conditions:

Yes No Is Protective Cover in Area 5 observed to be in same conditions compared to "baseline conditions"? If no, describe change(s) in conditions: _____

Yes No Are there bare spots, signs of erosion? (If yes, attach photographs and figure showing location and extent): Describe eroded area or areas of potholes: _____

Yes No Is there any Asbestos Containing Material (ACM) observed at the ground surface: _____

Other Observations: _____

Area 6 Conditions:

Yes No Is Protective Cover in Area 6 observed to be in same conditions compared to "baseline conditions"? If no, describe change(s) in conditions: _____

Yes No Are there bare spots, signs of erosion, or large potholes in pavement? (If yes, attach photographs and figure showing location and extent): Describe eroded area or areas of potholes: _____

Yes No Is there any Asbestos Containing Material (ACM) observed at the ground surface: _____

Other Observations: _____

Project	W.R. Grace & Co.	Report No.	22
Location	62 Whittemore Avenue, One Alewife Center, 134 Alewife Brook Parkway	Date	12 October 2009
Address	Cambridge, Massachusetts	Page	4 of 6
Client	W.R. Grace & Co.	File No.	10063-066
Weather	Sunny	Temperature	55°
Field Rep.	Jennifer Sweet, Dave Croce		
LSP	John R. Kastrinos, P.G., LSP		

Area 7 Conditions:

Yes No Is Protective Cover in Area 7 observed to be in same conditions compared to "baseline conditions"? If no, describe change(s) in conditions: _____

Yes No Are there bare spots or signs of erosion? (If yes, attach photographs and figure showing location and extent): Describe eroded area or areas of potholes: _____

Yes No Is there any Asbestos Containing Material (ACM) observed at the ground surface: _____

Other Observations: _____

Area 8 Conditions:

Yes No Is Protective Cover in Area 8 observed to be in same conditions compared to "baseline conditions"? If no, describe change(s) in conditions: _____

Yes No Are there signs of erosion or large potholes in pavement? (If yes, attach photographs and figure showing location and extent): Describe eroded area or areas of potholes: _____

Yes No Is there any Asbestos Containing Material (ACM) observed at the ground surface: _____

Other Observations: _____

PROTECTIVE COVER MONITORING PLAN INSPECTION REPORT

Project	W.R. Grace & Co.	Report No.	22
Location	62 Whittemore Avenue, One Alewife Center, 134 Alewife Brook Parkway	Date	12 October 2009
Address	Cambridge, Massachusetts	Page	5 of 6
Client	W.R. Grace & Co.	File No.	10063-066
Weather	Sunny	Temperature	55°
Field Rep.	Jennifer Sweet, Dave Croce		
LSP	John R. Kastrinos, P.G., LSP		

2. Interview with Owner Representative

Name of Owner's Representative interviewed: DAVE CROCE

Any new buildings or structures on the Site? NO

Any changes in use of the existing buildings? NO

Any changes in use of un-built areas? NO

Any evidence of active recreation? NO

Any current activities that would degrade the Protective Cover? NO

Any evidence of property use for cultivation of fruits and vegetables for human consumption? NO

Has there been any emergency utility work conducted since the last inspection? NO

3. Maintenance/Repair Actions to be Taken

Yes | No | Were changes in the Protective Cover noted during the inspection that require actions to be taken to maintain and/or repair the Cover? If yes, describe: _____

4. Other Comments:

PROTECTIVE COVER MONITORING PLAN INSPECTION REPORT

Project	W.R. Grace & Co.	Report No.	22
Location	62 Whittemore Avenue, One Alewife Center, 134 Alewife Brook Parkway	Date	12 October 2009
Address	Cambridge, Massachusetts	Page	6 of 6
Client	W.R. Grace & Co.	File No.	10063-066
Weather	Sunny	Temperature	55°
Field Rep.	Jennifer Sweet, Dave Croce		
LSP	John R. Kastrinos, P.G., LSP		


ATTACHMENTS:

(Check off attachments)

Figure 1: PCMP - Site Orthophoto

Photographs (List and note photo location/orientation on figure)


- _____
- _____


Haley & Aldrich, Inc.



- LEGEND**
- INSPECTION PHOTOGRAPHS
 - DIRECTION OF PHOTOGRAPH PHOTO NUMBER
 - EXISTING STRUCTURE
 - AREA OF INTEREST
 - EXISTING WATER BODY
 - APPROXIMATE LIMITS OF A.I.U.

- NOTES**
1. ALL LOCATIONS, DIMENSIONS, AND SITE FEATURES ARE APPROXIMATE
 2. 1/2 METER RESOLUTION ORTHOPHOTOGRAPHY FROM 7/1/2007 OBTAINED FROM THE OFFICE OF GEOGRAPHIC AND ENVIRONMENTAL INFORMATION (MASSGIS), COMMONWEALTH OF MASSACHUSETTS EXECUTIVE OFFICE OF ENVIRONMENTAL AFFAIRS



HALEY & ALDRICH
 W.R. GRACE & CO. - CONN.
 82 WHITTEMORE AVENUE
 PROTECTIVE COVER MONITORING PLAN
 CAMBRIDGE, MASSACHUSETTS

SITE ORTHOPHOTO

SCALE AS SHOWN
 OCTOBER 2009

FIGURE 1



AI-1



AI-2



AI-3



AI-4



AI-5



AI-6



A1-7



A1-8



A2-1



A2-2



A2-3



A2-4



A3-1



A3-2



A3-3



A4-1



A4-2



A4-3



A4-4



A4-5



A5-1



A5-2



A5-3



A7-1



A7-2



A8-1



A8-2



A8-3



A8-4